

## LIST OF VEHICLES RECOMMENDED FOR 2019 BOARDING EXERCISE

SN	VEHICLE NO	MAKE OR TYPE	YEAR PURCH	ENGINE NO	CHASIS NO	LOCATION	REMARK	FMW AUCTION VALUE
1	FG 662 V01	Toyota Prado	2008	2TR- 0641631	JTEBL2913 851203	Headquarters	Engine problem	
2	FG 613 V01	Toyota Prado	2007	367568	305055497	Headquarters	Engine problem	
3	FG 631 V01	Toyota Prado	2008	2TR- 0579079	JTEBL2917 85105430	Headquarters	Engine problem	
4	FG 656 V01	Toyota Prado	2007	2TR- 0634778	JTEBL2916 8511874	Headquarters	Engine problem	
5	FG 665 V01	Toyota Prado	2007	3TR- 0641062	JTEBL2912 85120237	Headquarters	Engine problem, steering, gear, axle and door	
6	FB 236 V01	Peugeot 407	2010	6217782 27	VE36DRFG 621778227	Headquarters	Engine problem, side glass and windscreen	
7	FG 599 V01	Mazda Pick U	2007	2832249	2260429544	Headquarters	Engine, electrical and tyres	
8	FG740 V01	Toyota Hilux 4x4	2011	2TR- 5051427	MROFX22 G1A105015 5	Abia	Has been repaired severally for engine and axle problems before 2019 General Elections but to no avail, as it broke down repeatedly thereafter. As we have to	

							contend with the current economic reality, this vehicle is not economically viable for further repair work. Hence, I advised the Commission to board it. It has also outlived its useful lifespan of more than five years,	
9	FG741V 01	Toyota Hilux 4x4	2011	2TR- 6953189	MROFX22 G6A105045 7	Abia	Has been repaired severally for engine and axle problems before 2019 General Elections but to no avail, as it broke down repeatedly thereafter. As we have to contend with the current economic reality, this vehicle is not economically viable for further repair work. Hence, I advised the Commission to board it. It has also outlived its useful lifespan of more than five years,	
10	FG 751 V01	Toyota Hilux 4x4	2010	2TR- 6957354	MROFX22 G5A104123 0	Abia	Has been repaired severally for engine and axle problems before 2019 General Elections but to no avail, as it broke down repeatedly thereafter. As we have to contend with the current economic reality, this vehicle is not economically viable for further repair work. Hence, I advised the Commission to board it. It has also outlived its useful lifespan of more than five years,	
11	FG 735	Toyota	2010	2TR-	MROFX22	Akwa Ibom	Accidentated since 2011 and worsen by the	

	V01	Hilux 4x4		6957190	G5A105124 4		effect of weathering. Items damaged include: Windscreen, damaged radiator, damage burnet, mount guard, front drill, radiator, yr dryer, body panel work and tires. Repairs/servicing not economically viable and, therefore, unserviceable.	
12	EMB 01M57 AK	Nissan Pick Up	2011	2TR- 5054422	MROFX22 GOA10500 34	Akwa Ibom	Accidentated since 2019 and worsen by the effect of weathering. Items damaged include: 4 Damaged engine, damaged chassis, damaged windscreen back and front, damaged side mirrors, damaged back tail, damaged burnet and tires. Repairs/servicing not economically viable and, therefore, unserviceable.	
13	FG 771 V01	Toyota Hilux 4 x4	2011	2TR- 6693535	MR0FX22 G89131940 8	Akwa Ibom	Accidentated since 2014 and worsen by the effect of weathering. Items damaged include: Brain box, double head light, damaged radiator, bumper (front), camber up and down, body panel work and tires. Repairs/servicing not economically viable and therefore, unserviceable.	
14	FG 755 V01	Toyota Hilux 4 x4	2011	2TR- 6947469	MR0FX226 5A1049719	Akwa Ibom	Accidentated since 2011 and worsen by the effect of weathering. Items damaged include:	

							Alternator, radiator, fan blade, dryer compressor, brake disk, 1 camber, steering box, shaft, mount guard, bumper, brain box, front drill, body panel work and tires. Repairs/servicing not economically viable and therefore, unserviceable.	
15	FG 773 V01	Toyota Hilux 4x4	2011	2TR- 6956816	MR0FX22 G1B105521 3	Anambra	Has knocked engine.	
16	FG 781 V01	Toyota Hilux 4x4	2011	2TR- 6949207	MR0FX22 G6A104989 1	Anambra	Has a knocked engine block.	
17	FG 731 V01	Toyota Hilux 4x4	2010	2TR- 5053171	MR0FX22 GXA10506 69	Cross River	The engine was damaged beyond repairs. Vehicle remains unserviceable.	
18	FG 368 V01	Toyota Hilux 4x4	2013	2TR- 7382848	AHTFX22 G60801748 5	Cross River	Vehicle was involved in an accident and greatly damaged to the extent that even when much effort and money was put into the repairs, it ended in futility.	
19	FG 903 V01	Toyota Hilux Pick Up	2011	2TR- 5070303	MROFX22 G4B105557 6	Delta	Not serviceable. It has the following issues: Engine knock, faulty complete steering system, faulty clutch plate, disc, radiator, brake drum, side mirrors, passender side and engine glass roller	

20	FGN 163 V01	Toyota Hilux Pick Up	2011	2TR- 5070303	MROFX22 GB105576	Ebonyi	Unserviceable because it has the following problems:  <ol style="list-style-type: none"> <li>1. Accidented</li> <li>2. Engine and gear system affected in the accident as well as front bumper</li> <li>3. Steering control remained stiff. The steering pump was badly affected and even after repairs movement of car is not smooth.</li> <li>4. No air conditioner</li> <li>5. Has not been in use at all since 2018.</li> </ol>	
21	FG 857 V01	Toyota Hilux Pick Up	2011	2TR- 7059535	AHFTX22 G08001055 4	Edo	Accidented 2018 and it is beyond economic repair because it has bad engine and axle problem.	
22	FG 318 U01	Toyota Hilux Pick Up	2011	2TR- 7059535	AHTFX22 G30801055 4	Edo	Accidented 2016/2017 and it is beyond economic repair because it has bad engine and axle problem.	
23	FG 98 U01	Toyota Hilux Pick Up	2011	2TR- 5049753	MROFX22 XA1049067	Enugu	Beyond economic repairs due to :  <ol style="list-style-type: none"> <li>1. Persistent fuel pump fault</li> <li>2. Brain box</li> <li>3. Engine knocked</li> <li>4. Has been parked for three years..</li> </ol>	
24	FG 91 V01	Toyota Hilux	2011	2TR- 5050298	MROFX22 G0A104928	Enugu	Beyond economic repair due to:  <ol style="list-style-type: none"> <li>1. Accidented that affected the chamber</li> </ol>	

		Pick Up			6		<ul style="list-style-type: none"> <li>2. c\Camber problem</li> <li>3. Engine knocked</li> <li>4. Has been parked for thtree years.</li> </ul>	
25	FG 95 V01	Toyota Hilux Pick Up	2011	2TR- 5050320 298	MROFX22 G0A104928 6	Enugu	<p>Beyond economic repair due to:</p> <ul style="list-style-type: none"> <li>1. Persistent electrical problem</li> <li>2. Brain box issues</li> <li>3. Engine knocked</li> <li>4. Has been parked for three years</li> </ul>	
26	FG 92 V01	Toyota Hilux Pick Up	2011	2TR- 6932246	MROFX22 G4A104976	Enugu	<p>Beyond economic repair due to:</p> <ul style="list-style-type: none"> <li>1. Accident that affected the front tyres not in the same position</li> <li>2. Engine knocked</li> <li>3. Gear problem</li> <li>4. Has been parked for three years.</li> </ul>	
27	FG 97 V01	Toyota Hilux Pick Up	2011	2TR- 6992135	MR0FX22 G4A104917 6	Enugu	<p>Beyond economic repair due to:</p> <ul style="list-style-type: none"> <li>1. Steering stiffness</li> <li>2. Gear problem</li> <li>3. Engine knocked</li> <li>4. Has been parked for three years.</li> </ul>	
28	FG 817 V01	Toyota Hilux 4 X 4	2011	2TR- 6939336	MR0FX226 8A1048659	Gombe	Completely broken down beyond economic repairs.	
29	FG 173 V01	Toyota Hilux	2011	2TR- 6992135	MROFX22 G5A105062	<b>Imo</b>	before I assumed duty. On enquiry I was told it had an engine knock and despite the	

		Pick Up			7		<p>huge sum invested in its repair it continued to fail and had become unserviceable.</p> <p>Just before the election we spent quit a lot of money to get the vehicle back on the road, but it functioned epileptically and broke down severally during the election. It has remained grounded since then as the cost of maintaining it was becoming prohibitive.</p>	
30	FG 375 V01	Toyota Hilux Pick Up	2011	2TR- 5068424	MROFX22 GXA10508 20	<b>Imo</b>	<p>This vehicle was grounded and abandoned before I assumed duty. On enquiry I was told it had an engine knock and despite the huge sum invested in its repair it continued to fail and had become unserviceable.</p> <p>Just before the election we spent quit a lot of money to get the vehicle back on the road, but it functioned epileptically and broke down severally during the election. It has remained grounded since then as the cost of maintaining it was becoming prohibitive.</p>	
31	FG 169 V01	Toyota Hilux Pick Up	2011	2TR- 5068424	MR0FX22 G3B105516 4	<b>Imo</b>	<p>I met the vehicle grounded and abandoned when I resumed duty. On enquiry I was told that the vehicle was accidented and that the front camber and chassis were irreparably damaged. An effort to reclaim the vehicle</p>	

							was not encouraging as it broke down severally within the election period. The mechanic advised that the only option was to dismantle te whole vehicle body and engine and transfer to a new chassis. The cost was very prohibitive.	
32	FG 179 V01	Toyota Hilux Pick Up	2011	2TR- 5068657	MROFX22 G6A105045 7	Imo	Again I inherited this vehicle grounded and abandoned. I was informed that the shaft and bearing was severely damaged. Before the election we repaired the vehicle, but it kept breaking down thereafter. Given the prohibitive cost of maintenance the vehicle was again grounded.	
33	FG 171 V01	Toyota Hilux Pick Up	2011	2TR- 6980450	AHTF22G3 08009565	Imo	The vehicle had an accident and I was informed it somersaulted several times. The body of the vehicle inclusive of the back and bucket are in bad shape.	
34	FG 377 V01	Toyota Hilux 4x4	2011	2TR- 7374391	AHTFX22 GX0801717 6	Kaduna	Due for auction	
35	FG 829 V01	Toyota Hilux Pick	2011	2TR- 6964411	AHTF22G5 B1052466	Katsina	It has no economic value and should be auctioned. The issues are: engine knocked, broken down electric suspension and transmission system.	

36	FG 284 U01	Toyota Hilux Pick	2011	5061815	MR0FX22 G5B105346 2	Katsina	It has no economic value and should be auctioned. The issues are: general overhaul with repairs of transmission electric, suspension system and general body work.	
37	FG 83 V01	Toyota Hilux 4x4	2TR- 695311 3	MROFX 22G5A1 050501	Toyota Hilux	Kwara	Unserviceable, because it has faultydiscarbonised engine, master brake axle, brake drum, brake pot, clutch plate, disc, front suspension andbrake pad and linig.	
38	FG 100 V01	Toyota Hilux 4x4	2TR- 694220 2	MROFX 22G3A1 049072	Toyota Hilux	Kwara	Unserviceable , because it has faulty discarbonized engine , released bearing, power steering pump, steering rzck, ball joint, centre arm and rear brake drum.	
39	FG 305 V01	Toyota Hilux 4x4	2TR70 22178	AHTFX 22G808 010033	Toyota Hilux	Kwara	Unserviceable, because it has faulty discarbonized engine, door side glass, brake system and gear system.	
40	FG 889 V01	Toyota Hilux 4x4	2TR69 81010	AHTFX 22GXO 8009577	Toyota Hilux	Kwara	Unserviceable, because it has faulty duscarbonized engine, chais, suspension front, rear shock absorber, and clutch pot. Also this vehicle is accidented in 2013, which resulted in axle problem,	
41	FG 76 V01	Toyota Hilux Pick-Up	1997	SE1313 48	MAT34907 0WIL0048	Ondo	Knocked engine and parked for almost ten years. Its unserviceable.	
42	FG 457	Toyota	2011	2TR-	MROFX22	Yobe	Damaged by Boko Haram. Problems	

	V01	Hilux Pick Up		6949130	G3A810499 31		include: accidented, engine, chasis and back axle	
43	FG 978 V01	Toyota Hilux Pick Up	2011	2TR- 5050459	MR0FX22 G3A104950 8	Yobe	Damaged by Boko Haram. Problems include: chasis, brain box, bvacck axle and engine.	
44	FG 990 V01	Toyota Hilux	2011	2TR- 6949130	MR0FX229 381049931	Yobe	Damaged by Boko Haram. Problems include: Engine, chasis, back axle, had and accident earlier.	

**ADDENDUM FOR 2019 BOARDING EXERCISE**

<b>S/N</b>	<b>VEHICLE</b>	<b>MAKE OR TYPE</b>	<b>YEAR</b>	<b>ENGINE NO.</b>	<b>CHASIS NO.</b>	<b>LOCATION</b>	<b>REMARKS</b>	<b>FMW AUCTION VALUE</b>
1.	EMB01M02 HQ	TOYOTA L/C V8	2015	0436483-IVR	JTMHX09J7 E5044131	HQ	BER	
2.	EMB01M03 HQ	TOYOTA L/C V8	2015	0435925-IVR	JTMHX09J 6E 5043990	HQ	BER	
3	EMB01M04 HQ	TOYOTA L/C V8	2015	043592I VR	JTMHX09J 8E 5044154	HQ	BER	
4	EMB01M06 HQ	TOYOTA L/C V8	2015	0359876 1-IVR	JTMHX09J 7E 030681	HQ	BER	
5	EMB 01M 07HQ	TOYOTA L/C V8	2015	0359876 -IVR	JTMHX09JA05 030681	HQ	BER	
6	EMB01M11 HQ	TOYOTA L/C V8	2015	14R-0436586	JTMHX09J 6E 044143	HQ	BER	
7	EMB01M42 HQ	TOYOTA L/C V6	2015	IGR-FE3956 ML521	JTMHU09J4E 5084031	HQ	BER	
8	FG 09 VOI	TOYOTA L/C V6	2011	IGR-A147503	JTMHX09J3E5 0394337	HQ	BER	
9	FG 494 VOI	M/BENZ 711 TRUCK	2006	654529	448563	KWARA	BER	
10.	FG 265 U01	TOYOTA HILUX (4X4) PICK-UP	2011	2TR-6952593	MROFX22GOA 1050387	BENUE		
11.	FG 266 U01	TOYOTA HILUX (4X4) PICK-UP	2011	2TR-5063884	MROFX22G6B 1321857	BENUE		

12.	FG 268 U01	TOYOTA HILUX (4X4) PICK-UP	2011	2TR- 6955411	MROFX22G4A 1050778	BENUE		
13.	FG 271 U01	TOYOTA HILUX (4X4) PICK-UP	2011	2TR- 5065287	MROFX22G8B 11322136	BENUE		
14.	EMB 01M 56 BN	NISSAN DOUBLE CABIN	2015	KA2482 34885X	ADNCDUD22Z OO45262	BENUE		